



NOTICE: Notch Sentinel Harness (all models)



The Issue

It has come to our attention that two (2) Notch Equipment Sentinel harnesses have had the plastic housing on the waist buckle come apart. This plastic housing is used to keep the waist buckle seated in position and is not part of a primary life safety system. The buckle housing failure, while alarming, does not impact the bridge, your primary life safety system, which remains 100% operable.

At Notch Equipment we take your safety seriously. That is why we are sending out this notice for inspection. We recommend you add a visual inspection to the waist buckle of your harness every day, in addition to your daily safety inspections.

The plastic piece on top of the buckle can start to pull away from the metal back piece. With the waste belt tensioned as instructed in the user instructions, even with the plastic top piece of the buckle missing, the buckle by design cannot release tension on the user.




Notch Equipment
496 Gallimore Dairy Rd, Ste D
Greensboro NC 27409



Inspection Method

Please inspect the waist belt buckle for any looseness, or gap between plastic top of the buckle and the metal bottom



The Remedy

If you identify any separation between the plastic top piece and metal back piece of the triple lock buckle on your Sentinel harness, please remove it from service immediately and return it for repair or replacement by contacting info@notchequipment.com or calling (833) 795-0604. Thank you for putting your trust in Notch Equipment.

6/11/2021